

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7



FIG. 8




FIG. 9

DOORSNEDE A-B
BIJ AFHECHTINGEN




FIG. 10




FIG. 11






FIG. 12



ALLEEN DE LINKERHEFT IS GETEKEND.




FIG. 13